


C25- SMOOTH STEPPER LPT BOARD Rev. 1.1

User manual Rev. 1.1



1. Overview

This board serves as a basic breakout board for the Smooth Stepper Board.

2. Features

- **34 inputs and outputs on 2 ports.**
- **Full access to all the pins of the Smooth Stepper Board.**

- **Connects directly to the Smooth Stepper (from Warp9).**

The board is provided with sockets that allow the Smooth Stepper Board to be plugged directly into this board. No ribbon cables required. When using the Smooth Stepper board

there is no need to use an additional power supply to power the board. It will draw power from the Smooth Stepper board.

- ***Built-in Passive Low Pass Filters for the all inputs.***

This board includes low pass filters to reduce the effect of the noise from the drivers or other devices over the inputs signals.

- ***All TTL 5VDC signals.***

Interface directly with parallel port interface products and other CNC4PC cards. 5VDC (TTL) cards are very common among automation devices.

- ***Input and output pins with close by ground connections.***

Forget about grounding problems. Easily connect your pin by using your close by ground connection. No need to be an electronics expert to ground all your stuff.

- ***Screw-On connections for all terminals.***

You only have to screw-on the wires to make all your connections.

3. Specifications.

DIGITAL INPUT SPECIFICATIONS	
Numbers of inputs	5 on Port1, 13 on Port2
On-state voltage range	2 to 5V DC
Maximum off-state voltage	0.8V

DIGITAL OUTPUT SPECIFICATIONS	
Number of outputs	12 on Port1, 4 on port2
Maximum output voltage	(5V power supply voltage) + 0.5V
Maximum off-state voltage	0.44 V

4. Functional Block Diagrams

4.1 Inputs 10, 11, 12 13 and 15 (Port 1 and Port 2) simplified functional block diagram




Fig. 1 Simplified functional block diagram.

Note: The Smooth Stepper includes an Schmitt Trigger in those input pins.

4.2 Inputs 2-9 (Port 2) simplified functional block diagram




Fig. 2 Simplified functional block diagram for the outputs 2-9.

Using an RC Low Pass filter followed by a Schmitt Trigger gate will reduce the effect of the noise from driver or other devices. This eliminates the high frequency components of the noise and generating a fast changing signal.


4.2 Outputs 1, 14, 16 and 17 (Port 1 and 2) and outputs 2-9 (port 1).

All those pins are directly routed to the C25 output terminals.

5. Wiring diagrams

Different kind of sensors and switches can be connected to inputs board, but this board support only TTL signal. If you need to connect devices that generates 12V or 24V signals in some cases is necessary add external resistors.

5.1 Connecting Switches or push button (Only for pins 2-9, port 2).



5.2 Connecting Switches or push button (Pins 11, 12, 13 and 15, Ports 1 and 2).




Fig. 3 Wiring diagram to connect switches.

5.3 Connecting NPN sensors (For any input).




Fig. 7 Wiring diagram to connect NPN open collector proximity sensors.




Fig. 8 Wiring diagram to connect in parallel NPN open collector proximity sensors.

Connecting NPN open collector proximity sensor with the C25	
R1 Value (12V)	R1 Value (24V)
Aprox. 10K Ω	Aprox. 25K Ω





Fig. 9 Wiring diagram to connect NPN proximity sensors with internal pull up resistor.

Some NPN proximity sensors have an internal pull-up resistor (R1). It is necessary to know its value in order to safely connect the sensor with the BOB. Follow this recommendation:

Connecting NPN open collector proximity sensor with the C25	
(R1+R2) Value (12V)	(R1+R2) Value (24V)
Aprox. 10K Ω	Aprox. 25K Ω

Calculating the R1 value.

Note: Rx is the unknown resistor value.



$$R_X = V_{EX} \cdot (R/V) - R \quad (1)$$

Where:

V_{EX} is the external power supply voltage

V is the voltage across the R resistor

A voltmeter is required to calculate the internal resistor value (R_X). Do the connection as are shown in the figure above and do the calculations using the equation (1).

Note. R value has to be known to do this operation. A 4.7KOhm@1/2W is recommended.

For example, if you are using a 12V power supply (V_{EX}), and use a 4.7KOhm as external resistor (R), and the voltage across R is 6V, using the equation 1, the R_X value is 4.7KOhm.

5.4 Connecting PNP sensors (For any input).




Fig. 10 Wiring diagram to connect PNP proximity sensors

Connecting PNP proximity sensor with the C25	
R Value (12V)	R Value (24V)
Aprox. 10K Ω	Aprox. 25K Ω

5.5 Other connection (For any input).

Other connections can be implemented by setting the inputs with pull-up resistor. In this case connect an external 4.7KOhm resistor between the input terminal and the 5V terminal.




Fig. 11 Wiring diagram to do an "Auto Tool Zero"

7. Troubleshooting.

SYMPTOM 1: THE BOARD DOES NOT REACT TO THE SIGNAL.

POSSIBLE CAUSE	POSSIBLE SOLUTIONS
<ul style="list-style-type: none"> - Pin conflict or mach3 configuration. It is possible that the port address used for the pin is not right, or that there is a pin conflict with the. That is that you are using that same pin twice. (it could be assigned to a different function). 	<ul style="list-style-type: none"> - Check that the pin you are using is not been used anywhere else in your setup. Got to motor output and output signals, and check all the entries.
<ul style="list-style-type: none"> - The signal or frequencies are not getting to the board. 	<ul style="list-style-type: none"> - Try a different cable. - Test the pins in the cable (before they reach the breakout board) with a multimeter.

SYMPTOM 2: THERE IS NOISE IN THE SYSTEM, OR THE MOTORS DO NOT MOVE SMOOTHLY.

POSSIBLE CAUSE	POSSIBLE SOLUTIONS
<ul style="list-style-type: none"> - There could be a short that could be draining the power to the board. 	<ul style="list-style-type: none"> - Check that there are no hot spots in the board or it's connections. - Measure the board's power consumption, it should be less than 200mA (depending on the features used).

SYMPTOM 3: A I/O PIN MIGHT NOT BE WORKING.

POSSIBLE CAUSE	POSSIBLE SOLUTIONS
<ul style="list-style-type: none"> - A chip may have gone bad. These buffers could act as fuses for the signals, and they can go bad because of noise spikes or even strong static. 	<ul style="list-style-type: none"> - These chips are inexpensive and readily available. You can order them here: http://www.cnc4pc.com/Store/osc/index.php?cPath=38_43.

	<ul style="list-style-type: none">- Carefully moving chips around and checking if the problem moves around could be a way of figuring out if this is the case.
--	--

