



USB  
CONNECTION



Note: If using PORT 4, use an external  
and set the jumper for powering the  
board with the external power supply  
Otherwise, the board may be  
powered from the breakout board.



Breakout Board  
(C32,C23,C62)

# CNC<sup>4</sup>PC

<http://www.cnc4pc.com>

Designed: YAC

Date: JUL-28 -2014

Revised:

Date:

Item: KT-UC300

Ver.:

Description:

UC300 CONTROLLER